

# Bactericidal Agent and Food Service Equipment Information System



## Approved Machines for Heat-treatment of Milk

No	Brand	Model	Hong Kong Agent	Manufacturer	Approving Condition	Date of Approval
1						
2	Alfa Laval Plate Heat Exchanger	H10 - RC	Nestle Dairy Farm Limited, 18 Wang Lok Street, Yuen Long Industrial Estate, N.T.	Alfa Laval Thermo Inc., 5400 Internation Trade Drive Richmond, Virginia 23231, USA	<p>(a) The method of pasteurization of milk and milk beverages should follow the Schedule to the Milk (Regional Council) Bylaws;</p> <p>(b) the sanitizing and cleansing procedures should be strictly followed;</p> <p>(c) the bacteriological standard of milk and milk beverages should abide by Bylaws 5 of the Milk (Regional Council)Bylaws;</p> <p>(d) arrow signs should be painted on the piping of the heat treatment plant to indicate the flow pattern of its contents; and</p> <p>(e) a copy each of the sanitizing and cleaning instructions for the heat treatment plant should be displayed near the plant.</p>	13 February, 1996
3	Alfa-Laval	C6-SR	Tetra Pak China Ltd. Room	Tetra Pak Dairy & Beverage System AB	--	8 August, 2004

			2313-15, Cityplaza One, 1111 King's Road, Taikooshing, Hong Kong.	P.O. Box 64, SE-221 86 Lund, Sweden.		
4	Alfa-Laval	H7-RC1	Tetra Pak China Ltd. Room 2313-15, Cityplaza One, 1111 King's Road, Taikooshing, Hong Kong.	Tetra Pak Dairy & Beverage System AB P.O. Box 64, SE-221 86 Lund, Sweden.	--	8 August, 2004
5	Alfa-Laval	H7-RC2	Tetra Pak China Ltd. Room 2313-15, Cityplaza One, 1111 King's Road, Taikooshing, Hong Kong.	Tetra Pak Dairy & Beverage System AB P.O. Box 64, SE-221 86 Lund, Sweden.	--	8 August, 2004

6	ALFA-LAVAL (Product of Sweden)	Steritherm P6	Tetra Pak China Ltd. 2313-15 Cityplaza One, 111 King's Road, Taikooshing, H.K.	ALFA-LAVAL Corporate AB located at Lund, Sweden	-	11 November, 2003
7	APV	H17	APV Systems Room 703, AIA Plaza, 18 Hysan Avenue, Causeway Bay, Hong Kong.	APV Products, Heat Transfer, 8 Platinvej 8, DK-6000 Kolding, Denmark.	--	8 August, 2004
8	APV Heat Treatment Plant/ Homogenizer	5DS650	Nestle Dairy Farm Limited, 18 Wang Lok Street, Yuen Long Industrial	APV Crepaco Inc. (USA), 9525 W. Bryn Mawr Avenue Rosemount, Illinois 60018, USA	(a) The method of pasteurization of milk and milk beverages should follow the Schedule to the Milk (Regional Council) Bylaws;  (b) the sanitizing and cleansing procedures should be strictly followed;  (c) the bacteriological standard of milk and milk beverages should abide by Bylaws 5 of the Milk (Regional Council)Bylaws;  (d) arrow signs should be painted on the piping of the heat treatment plant to indicate the flow pattern of its contents; and	13 February, 1996

			Estate, N.T.		(e) a copy each of the sanitizing and cleaning instructions for the heat treatment plant should be displayed near the plant.	
9	Bratlan II Autometic Dairy	-	Affix Ltd., 603, Kam Chung Bldg., 54, Jaffe Road, Hong Kong	Gay's (Hampton) Ltd., Oldfield Road, Hampton, Middlesex, England.	-	16 September, 1983
10	Cherry-Burell Unitherm IV	-	(Note : this machine was ordered direct from the manufacturer by the Kowloon Dairy Ltd. (L/M 16 in RSD 6/HQ 502/77 refers))	Cherry-Burrell Corporation, 2400 Sixth Street SW, Cedar Rapids, 1A 52406-3004, U.S.A.	-	11 April, 1987
11	Mallinson-Read (M.R.) 700	-	-	David Mallinson Engineering Ltd.,	-	1 December, 1986

	litres dairy/farm pasteuriser for heat-treatment of milk			New House Farm, High Flatts, Huddersfield, HD8 8XD		
12	Milk Heat-treatment Plant	Alfa-Laval Steritherm M-6	Alfa-Laval (Hong Kong) Ltd., Suite 701, Guardian House, 32, Oi Kwan Road, Happy Valley, Hong Kong.	Alfa-Laval Food & Dairy Engineering AB, S-22103 Lund, Sweden	-	5 September, 1988
13	Sigma	27TB	Swire Coca Cola HK Ltd. 17-19 Yuen Shun Circuit, Siu Lek Yuen, Shatin, N.T.	API Schmidt-Bretten GmbH & Co-KG (P.O. Box 1580 75005 Bretten, Germany.)	--	8

14	STORK	3000	Vitasoy International Holdings Limited 1 Kin Wong Street, Tuen Mun, N.T.	Stork Amsterdam B.V. Postbus 759 1000 AT Amsterdam The Netherlands	--	28 September, 2004
15	STORK	Sterideal 8000-B	Rootic International Limited Unit 704, East Ocean Centre, 98 Granville Road, Hong Kong.	Stork Food & Dairy System Ketelstratt 2, 1021 JX Amsterdam, Netherlands.	Nil	14 September, 2005
16	Stork Sterideal	5000-B	Rootic Limited, 504B, Tung Ying Building, 100 Nathan Road, Tsim	Stork Amsterdam B.V. Ketelstraat 2, 1021 JX Amsterdam, The Netherlands	-	21 October, 1994

			Sha Tsui, Kowloon.			
17	Tetra Therm Aseptic VTIS 100	Tetra Therm Aseptic VTIS 100	Tetra Pak China Ltd. Suite 2313-15, Cityplaza One, 1111 King's Road, Taikooshing, Hong Kong.	Tetra Pak Dairy & Beverage Systems, AB, located at Lund, Sweden.	The heat treatment apparatus can only be used for sterilization of milk and milk beverage by the Ultra High Temperature Method and by indirect heating.	15 May, 2008