


Roof gutters

Causes of Mosquito breeding:


- * Poor gradient.
- * Gutter is not maintained and blocked with leaves or silt.
- * The metal gutter warped and impeded water flow.



Sand traps

Causes of Mosquito breeding:

- * The base of the sand trap is designed to trap sand, silt etc. Water collected and hold at the base together with silt.
- * Water collected at the base because of blocked outlets.



FEHD



Subterranean pits and Chambers

Cause of Mosquito breeding:


- * Water enters the chambers below ground through the key holes or gaps.



Anti-bumping tyres

Cause of Mosquito breeding:

- * Water accumulated in the hollows of the tyres.



FEHD



Water storage tanks

Cause of Mosquito breeding:

- * Inspection cover is not properly closed.



FEHD



Water taps

Causes of Mosquito breeding:

- * Water dripped from leaking valves and accumulated at the chamber base.
- * Water collected in the hollow of the cover.
- * Collection of water on the uneven ground due to water dripped from leaking valves.

