

**Refusal Reason in respect of**  
**紫竹林觀音堂 (No known English name)'s**  
**Temporary Suspension of Liability Application**

- (i) This Temporary Suspension of Liability (TSOL) application does not comply with the requirement under Section 21(3) of the Private Columbaria Ordinance (PCO) as the applicant fails to submit documents to prove to the satisfaction of the Private Columbaria Licensing Board (PCLB) that the columbarium has been certified, by a qualified professional, as not posing any obvious or imminent danger in terms of building safety;
- (ii) this TSOL application does not comply with the requirements under Sections 23(1) and 25 of the PCO as the applicant fails to submit the proposed plans in compliance with the requirements specified in the “Application Guide for Private Columbarium Licence and Other Specified Instruments” in accordance with the specified requirements of the PCLB; and
- (iii) this TSOL application does not comply with the requirement under Section 23(1) of the PCO as the applicant fails to submit an action plan for achieving compliance with the requirements of the Exemption application in accordance with the specified requirement of the PCLB [Note: If the application for TSOL is submitted with an application for Exemption and any application requirements for Exemption have not been met, the applicant should submit an action plan (with timetable) setting out the necessary steps to be taken to achieve compliance with the application requirements for Exemption in a timely manner] and the application summary for TSOL.